



Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2016 - Lake Leschenaultia and Jane Brook

LGA/ Managing Authority	Water Body	Site Code	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	Min No. Samples 2016-2017
Shire of Mundaring	Lake	MN3/052	Lake Leschenaultia - Beach	2012-2016	81	9	A	40	21	Moderate	Good (a)	Green	Collect 5-10 rainfall (24-48hrs) samples	13
Shire of Mundaring	Lake	MN3/053	Lake Leschenaultia - West Beach	2012-2016	81	10	A	41	21	Not Avail	Not Avail	Green	Collect 5-10 rainfall (24-48hrs) samples	13
Shire of Mundaring	Brook	MN3/008	Jane Brook - End Falls Rd	2012-2016	24	1350	D	1549	374	Not Avail	Not Avail	Red		
Shire of Mundaring	Brook	MN3/009	Jane Brook - Falls Park	2012-2016	24	1050	D		386	Not Avail	Not Avail	Red		
Shire of Mundaring	Brook	MN3/010	Jane Brook - Byfield Rd	2012-2016	24	1800	D		346	Not Avail	Not Avail	Red		
Shire of Mundaring	Brook	MN3/011	Jane Brook - Stoneville Rd	2012-2016	24	620	D	1609	274	Not Avail	Not Avail	Red		
Shire of Mundaring	Brook	MN3/012	Jane Brook - Sexton Rd	2012-2016	24	4150	D		863	Not Avail	Not Avail	Red		