

## Recreational Waters Bacterial Water Quality Sampling Program Site Status Report October 2013: Metropolitan Oceans

Site Code	Managing Authority	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assessment Category (SAC)	SAC Key Factor	Min No. LGA Samples Required 2013-2014	SAC Status Comments	Provisional Classification	Provisional Colour
EV3/718	Cambridge	City Beach	2007-2012	48	5	A	33	17	Low	Rainfall	5	Collect 5 rainfall (within 24hrs) samples	Very Good	Green
EV3/719	Cambridge	Floreat Beach	2008-2013	47	6	A	34	14	Low	Rainfall	5	Collect min 5-10 rainfall (24-48hrs) samples	Very Good	Green
EV3/754	Cambridge	City Beach North	2008-2013	48	70	B	700	20	Low	Rainfall	12	Collect min 5-10 rainfall (24-48hrs) samples	Very Good	Green
CK3/997	Cockburn	Port Coogee	2008-2013	38	110	B	700	34	Moderate - F/up	Rainfall	12	Collect min 5-10 rainfall (24-48hrs) samples	Good	Green
EV3/709	Cockburn	Coogee Beach	2008-2013	60	3	A	25	13	Moderate	Rainfall	5	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green
EV3/710	Cockburn	C.Y.O'Connor Beach	2008-2013	62	90	B	243	49	Moderate	Rainfall	12	Collect 10 rainfall (24-48hrs) samples	Good	Green
EV3/752	Cockburn	Jervoise Bay Beach	2008-2013	60	20	A	62	20	Moderate	Rainfall	12	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green
EV3/716	Cottesloe	Cottesloe Beach	2008-2013	59	50	B	132	33	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Green
EV3/753	Cottesloe	Cottesloe North	2008-2013	58	28	A	193	10	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Green
EV3/711	Fremantle	South Beach	2008-2013	66	70	B	169	40	Moderate	Rainfall	12	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green
EV3/713	Fremantle	Fremantle Swimmers Beach	2008-2013	63	9	A	41	16	Moderate	Rainfall	12	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green
EV3/714	Fremantle	Port Beach	2007-2012	60	2	A	30	10	Moderate	Rainfall	5	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green
EV3/715	Fremantle	Leighton Beach	2008-2013	63	2	A	20	10	Moderate	Rainfall	5	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green

## Recreational Waters Bacterial Water Quality Sampling Program Site Status Report October 2013: Metropolitan Oceans

Site Code	Managing Authority	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assessment Category (SAC)	SAC Key Factor	Min No. LGA Samples Required 2013-2014	SAC Status Comments	Provisional Classification	Provisional Colour
EV3/725	Joondalup	Hillarys South Break	2008-2013	64	16	A	56	18	Moderate	Rainfall	12	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green
EV3/728	Joondalup	Hillarys South Swim	2008-2013	64	135	B	304	67	Moderate	Rainfall	12	Collect 10 rainfall (24-48hrs) samples	Good	Green
EV3/729	Joondalup	Hillarys Middle Swim	2008-2013	65	60	B	129	38	Moderate	Rainfall	12	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green
EV3/730	Joondalup	Hillarys North Swim	2008-2013	65	65	B	796	20	Moderate	Rainfall	12	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green
EV3/731	Joondalup	Pinnaroo Point	2008-2013	65	125	B	451	64	Moderate	Rainfall	12	Collect 10 rainfall (24-48hrs) samples	Good	Green
EV3/732	Joondalup	Mullaloo Beach	2008-2013	65	2	A	24	14	Moderate	Rainfall	5	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green
EV3/733	Joondalup	Korella Street	2008-2013	65	24	A	92	20	Moderate	Rainfall	0	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green
EV3/736	Joondalup	Burns Beach	2008-2013	64	55	B	219	10	Moderate	Rainfall	12	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green
EV3/758	Joondalup	Sorrento Beach (Surf Club)	2008-2013	60	2	A	21	12	Moderate	Rainfall	5	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green
EV3/706	Kwinana	Naval Base	2008-2013	61	34	A	125	10	Moderate	Rainfall	12	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green
EV3/751	Kwinana	Kwinana Beach	2007-2012	70	9	A	39	15	Moderate	Rainfall	5	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green
EV3/717	Nedlands	Swanbourne Beach	2008-2013	72	55	B	172	30	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Green

## Recreational Waters Bacterial Water Quality Sampling Program Site Status Report October 2013: Metropolitan Oceans

Site Code	Managing Authority	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assessment Category (SAC)	SAC Key Factor	Min No. LGA Samples Required 2013-2014	SAC Status Comments	Provisional Classification	Provisional Colour
EV3/701	Rockingham	Rockingham Beach	2008-2013	78	50	B	118	32	Low	Rainfall	12	Send stormwater drain monitoring results	Very Good	Green
EV3/750	Rockingham	Palm Beach (Next to Jetty)	2008-2013	65	2	A	24	14	Moderate	Rainfall	5	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green
EV3/760	Rockingham	North Hymus	2008-2013	66	45	B	115	30	Moderate - F/up	Rainfall	12	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green
RK3/012	Rockingham	Waikiki Beach	2008-2013	83	32	A	98	22	Low F/up	Rainfall	12	Collect min 5-10 rainfall (24-48hrs) samples	Very Good	Green
RK3/027	Rockingham	Secret Harbour Surf Club	2008-2013	66	20	A	59	21	Outstanding	Rainfall	12	Collect min 5-10 rainfall (24-48hrs) samples	Very Good	Green
EV3/720	Stirling	Scarborough Beach	2008-2013	58	2	A	20	10	Moderate	Rainfall	5	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green
EV3/721	Stirling	Trigg Island	2008-2013	52	2	A	22	14	Moderate	Rainfall	5	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green
EV3/722	Stirling	Mettams Pool	2008-2013	64	40	A	593	10	Moderate	Rainfall	12	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green
EV3/723	Stirling	Hamersley Pool	2008-2013	48	20	A	81	10	Moderate	Rainfall	12	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green
EV3/724	Stirling	Watermans Beach	2007-2013	56	2	A	17	11	Moderate	Rainfall	5	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green
EV3/755	Stirling	Scarborough Beach North	2008-2013	53	2	A	16	10	Moderate	Rainfall	5	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green
EV3/756	Stirling	Scarborough Beach South	2008-2013	64	34	A	151	10	Moderate	Rainfall	12	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green
EV3/757	Stirling	South Trigg Beach	2008-2013	56	2	A	20	11	Moderate	Rainfall	5	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green

## Recreational Waters Bacterial Water Quality Sampling Program Site Status Report October 2013: Metropolitan Oceans

Site Code	Managing Authority	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assessment Category (SAC)	SAC Key Factor	Min No. LGA Samples Required 2013-2014	SAC Status Comments	Provisional Classification	Provisional Colour
EV3/739	Wanneroo	Quinns Rock	2008-2013	71	34	A	330	14	Moderate - F/up	Rainfall	12	Collect 10 rainfall (24-48hrs) samples	Good (a)	Green
EV3/759	Wanneroo	Mindarie (Claytons Beach)	2008-2013	69	6	A	37	10	Moderate	Rainfall	5	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green
EV3/762	Wanneroo	Yanchep Lagoon	2009-2013	76	22	A	157	10	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Green
EV3/763	Wanneroo	Two Rocks - Leemans Landing	2009-2013	74	55	B	6758	10	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Green
EV3/764	Wanneroo	Two Rocks (Sovereign Park)	2009-2013	76	2	A	20	10	Outstanding		5	Provide DoH Sanitary Inspection Report	Not Available	Green