

Recreational Waters Bacterial Water Quality Sampling Program Site Status Report October 2013: Regional Recreational Waters

| Site Code | Managing Authority | Site Name | Result Years | No. Samples | 95th %tile | Microbial Assess Category | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assessment Category (SAC) | SAC Key Factor | Min No. LGA Samples Required 2013-2014 | SAC Status Comments | Provisional Classification | Provisional Colour |
|-----------|------------------------|--------------------------------------|--------------|-------------|------------|---------------------------|----------------------------------|---------------------------------------|------------------------------------|----------------|--|---|----------------------------|--------------------|
| AM3/001 | Augusta-Margaret River | Margaret River (Canoe Landing) | 2009-2013 | 49 | 240 | C | 446 | 104 | Outstanding | | 16 | Provide DoH Sanitary Inspection Report | Not Available | Amber |
| AM3/006 | Augusta-Margaret River | Margaret River - Barrett St Weir | 2009-2013 | 49 | 180 | B | 241 | 78 | Outstanding | | 16 | Provide DoH Sanitary Inspection Report | Not Available | Amber |
| AM3/008 | Augusta-Margaret River | Gnarabup - Gas Bay Beach (near WWTP) | 2009-2013 | 49 | 50 | B | 700 | 16 | Outstanding | | 16 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| AM3/012 | Augusta-Margaret River | Gnarabup Beach (Jetty) | 2009-2013 | 51 | 230 | C | 1628 | 138 | Outstanding | | 14 | Provide DoH Sanitary Inspection Report | Not Available | Amber |
| AM3/014 | Augusta-Margaret River | Gracetown Beach | 2009-2013 | 51 | 95 | B | 534 | 44 | Outstanding | | 14 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| AM3/016 | Augusta-Margaret River | Flinders Bay (Redman Brook) | 2009-2013 | 50 | 50 | B | 148 | 29 | Moderate | Rainfall | 15 | Collect 10 rainfall (24-48hrs) & riverine samples | Good (a) | Green |
| AM3/021 | Augusta-Margaret River | Molloy Island Caravan Park | 2009-2013 | 50 | 36 | A | 85 | 30 | Outstanding | | 14 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| AM3/023 | Augusta-Margaret River | Hardy Inlet (Turner Caravan Park) | 2009-2013 | 51 | 380 | C | 778 | 159 | Outstanding | | 14 | Provide DoH Sanitary Inspection Report | Not Available | Amber |
| AM3/033 | Augusta-Margaret River | Margaret River (Rope Swing) | 2009-2012 | 31 | 8 | A | 38 | 19 | Outstanding | | 13 | Provide DoH Sanitary Inspection Report | Not Available | Green |

Recreational Waters Bacterial Water Quality Sampling Program Site Status Report October 2013: Regional Recreational Waters

| Site Code | Managing Authority | Site Name | Result Years | No. Samples | 95th %tile | Microbial Assess Category | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assessment Category (SAC) | SAC Key Factor | Min No. LGA Samples Required 2013-2014 | SAC Status Comments | Provisional Classification | Provisional Colour |
|-----------|--------------------|--------------------------------|--------------|-------------|------------|---------------------------|----------------------------------|---------------------------------------|------------------------------------|----------------|--|---|----------------------------|--------------------|
| BC3/001 | Bunbury | Jetty Bath West | 2009-2013 | 53 | 85 | B | 509 | 38 | Moderate | Rainfall | 13 | Collect 10 rainfall (24-48hrs) samples | Good | Green |
| BC3/012 | Bunbury | Koombana Beach | 2009-2013 | 51 | 55 | B | 143 | 34 | Moderate - F/up | Rainfall | 14 | Provide DoH Sanitary Inspection Report | Good | Green |
| BC3/017 | Bunbury | Surf Club Beach | 2009-2013 | 52 | 30 | A | 140 | 10 | Moderate - F/up | Rainfall | 13 | Collect min 5-10 rainfall (24-48hrs) samples | Good (a) | Green |
| BC3/018 | Bunbury | Hungry Hollow | 2008-2013 | 54 | 18 | A | 55 | 19 | Moderate - F/up | Rainfall | 13 | Provide DoH Sanitary Inspection Report | Good (a) | Green |
| BC3/025 | Bunbury | Ski Beach | 2009-2013 | 51 | 34 | A | 140 | 17 | Moderate - F/up | Rainfall | 14 | Collect min 5-10 rainfall (24-48hrs) samples | Good (a) | Green |
| BN3/023 | Busselton | Margaret Street Beach (Site 8) | 2009-2013 | 39 | 180 | B | 649 | 92 | Moderate | Rainfall | 13 | Collect 10 rainfall (24-48hrs) & riverine samples | Good | Green |
| BN3/024 | Busselton | Scout Beach (Site 6) | 2009-2013 | 42 | 60 | B | 165 | 33 | Outstanding | | 13 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| BN3/025 | Busselton | Forth Street Beach (Site 7) | 2009-2013 | 42 | 140 | B | 572 | 71 | Outstanding | | 13 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| BN3/028 | Busselton | Busselton Jetty Ocean 9 | 2009-2013 | 38 | 230 | C | 423 | 101 | Moderate - F/up | Rainfall | 14 | Collect 10 rainfall (24-48hrs) samples | Poor | Red |
| CP3/001 | Capel | Forrest Beach | 2009-2013 | 40 | 540 | D | 3699 | 358 | Moderate | Rainfall | 13 | Collect 10 rainfall (24-48hrs) samples | Poor | Red |
| CP3/002 | Capel | Peppermint Grove Beach | 2009-2013 | 40 | 38 | A | 140 | 10 | Moderate | Rainfall | 13 | Collect 10 rainfall (24-48hrs) samples | Good | Green |
| CP3/003 | Capel | Minningup Beach | 2009-2013 | 39 | 130 | B | 282 | 64 | Moderate | Rainfall | 13 | Collect 10 rainfall (24-48hrs) samples | Good | Green |
| CP3/004 | Capel | Dalyellup Beach | 2009-2013 | 39 | 55 | B | 700 | 10 | Moderate | Rainfall | 13 | Collect min 5-10 rainfall (24-48hrs) samples | Good (a) | Green |

Recreational Waters Bacterial Water Quality Sampling Program Site Status Report October 2013: Regional Recreational Waters

| Site Code | Managing Authority | Site Name | Result Years | No. Samples | 95th %tile | Microbial Assess Category | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assessment Category (SAC) | SAC Key Factor | Min No. LGA Samples Required 2013-2014 | SAC Status Comments | Provisional Classification | Provisional Colour |
|-----------|--------------------|----------------------------------|--------------|-------------|------------|---------------------------|----------------------------------|---------------------------------------|------------------------------------|----------------|--|--|----------------------------|--------------------|
| CP3/005 | Capel | Preston River (Boyanup) | 2009-2013 | 29 | 4650 | D | | 409 | High - F/up | Rainfall | 5 | Collect min 5-10 rainfall (24-48hrs) samples | Very Poor | Red |
| CP3/006 | Capel | Capel River (Mallokup Bridge) | 2009-2013 | 28 | 760 | D | 1877 | 325 | High - F/up | Rainfall | 13 | Collect 10 rainfall (24-48hrs) samples | Very Poor | Red |
| CN3/001 | Carnarvon | Carnarvon Town Beach | 2008-2013 | 33 | 310 | C | 668 | 136 | Outstanding | | 13 | Provide DoH Sanitary Inspection Report | Not Available | Amber |
| CN3/003 | Carnarvon | Facsine Beach | 2008-2013 | 28 | 60 | B | 110 | 41 | Outstanding | | 14 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| CN3/004 | Carnarvon | Before Yacht Club | 2008-2013 | 27 | 130 | B | 700 | 37 | Outstanding | | 15 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| CN3/041 | Carnarvon | Northwater DB Drive | 2011-2013 | 16 | 200 | B | 700 | 96 | Outstanding | | 13 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| CN3/043 | Carnarvon | Boat Harbour Snapper Jetty | 2011-2013 | 19 | 2 | A | 18 | 14 | Outstanding | | 14 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| CN3/044 | Carnarvon | Boat Harbour Wharf | 2011-2013 | 20 | 16 | A | 47 | 27 | Outstanding | | 16 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| CN3/045 | Carnarvon | Fascine Jetty | 2011-2013 | 20 | 12 | A | 42 | 25 | Outstanding | | 15 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| CN3/046 | Carnarvon | Pelican Point Beach | 2009-2013 | 11 | 2 | A | 19 | 13 | Outstanding | | 15 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| DA3/006 | Dandaragan | Jurien Boat Harbour Beach (West) | 2009-2013 | 34 | 45 | B | 142 | 28 | Moderate | Rainfall | 16 | Collect min 5-10 rainfall (24-48hrs) samples | Good | Green |
| DA3/007 | Dandaragan | Jurien Boat Harbour Beach (East) | 2009-2013 | 35 | 5 | A | 31 | 14 | Moderate | Rainfall | 15 | Collect 5 rainfall (within 24hrs) samples | Good (a) | Green |
| DA3/013 | Dandaragan | Dobbyn Park Beach | 2009-2013 | 35 | 30 | A | 89 | 21 | Moderate | Rainfall | 15 | Collect 5 rainfall (within 24hrs) samples | Good (a) | Green |

Recreational Waters Bacterial Water Quality Sampling Program Site Status Report October 2013: Regional Recreational Waters

| Site Code | Managing Authority | Site Name | Result Years | No. Samples | 95th %tile | Microbial Assess Category | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assessment Category (SAC) | SAC Key Factor | Min No. LGA Samples Required 2013-2014 | SAC Status Comments | Provisional Classification | Provisional Colour |
|-----------|--------------------|--|--------------|-------------|------------|---------------------------|----------------------------------|---------------------------------------|------------------------------------|----------------|--|---|----------------------------|--------------------|
| DK3/025 | Denmark | Peaceful Bay - Ocean/Drain | 2008-2013 | 14 | 32 | A | 83 | 27 | Outstanding | | | | Not Available | Green |
| DK3/025A | Denmark | Peaceful Bay - Ocean (South) | 2008-2013 | 13 | 175 | B | 700 | 166 | Outstanding | | | | Not Available | Green |
| DK3/025B | Denmark | Peaceful Bay - Ocean North of DK3/025 | 2008-2013 | 13 | 50 | B | 242 | 19 | Outstanding | | | | Not Available | Green |
| DK3/050 | Denmark | Wilson Inlet - Ocean Beach Caravan Park | 2012-2013 | 26 | 45 | B | 700 | 10 | Outstanding | | 13 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| DK3/051 | Denmark | Wilson Inlet - Yacht Club Gazebo 2 | 2012-2013 | 26 | 260 | C | 1222 | 141 | Outstanding | | 13 | Provide DoH Sanitary Inspection Report | Not Available | Amber |
| DK3/052 | Denmark | (Creek) Inlet Drive Bridge 3 | 2012-2013 | 32 | 1150 | D | 1961 | 401 | N/A | | | | | Red |
| DK3/053 | Denmark | Wilson Inlet - Rivermouth Caravan Park 4 | 2012-2013 | 26 | 1350 | D | 4375 | 655 | Outstanding | | 13 | Provide DoH Sanitary Inspection Report | Not Available | Red |
| DK3/054 | Denmark | Denmark River - Berridge Park 5 | 2012-2013 | 26 | 1100 | D | 1584 | 353 | Outstanding | | 13 | Provide DoH Sanitary Inspection Report | Not Available | Red |
| DK3/055 | Denmark | Wilson Inlet - Springdale Beach 6 | 2012-2013 | 25 | 100 | B | 333 | 52 | Outstanding | | 13 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| ES3/030 | Esperance | Bandy Creek Harbour | 2011-2013 | 27 | 580 | D | 1957 | 285 | Moderate - F/up | Rainfall | 13 | Collect 10 rainfall (24-48hrs) samples | Poor | Red |
| ES3/031 | Esperance | James St Groyne | 2011-2013 | 27 | 160 | B | 393 | 78 | Moderate - F/up | Storm water | 13 | Provide DoH stormwater drain monitoring results | Good (a) | Green |
| ES3/032 | Esperance | Port Authority Beach | 2011-2013 | 27 | 70 | B | 128 | 43 | Moderate | Storm water | 13 | Provide DoH stormwater drain monitoring results | Good (a) | Green |

Recreational Waters Bacterial Water Quality Sampling Program Site Status Report October 2013: Regional Recreational Waters

| Site Code | Managing Authority | Site Name | Result Years | No. Samples | 95th %tile | Microbial Assess Category | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assessment Category (SAC) | SAC Key Factor | Min No. LGA Samples Required 2013-2014 | SAC Status Comments | Provisional Classification | Provisional Colour |
|-----------|--------------------|---------------------|--------------|-------------|------------|---------------------------|----------------------------------|---------------------------------------|------------------------------------|----------------|--|--|----------------------------|--------------------|
| EX3/050 | Exmouth | Small Boat Harbour | 2008-2013 | 35 | 75 | B | 219 | 41 | Outstanding | | 13 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| EX3/051 | Exmouth | Exmouth Town Beach | 2008-2013 | 38 | 110 | B | 231 | 56 | Outstanding | | 13 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| EX3/055 | Exmouth | Marina - Pens 5 & 6 | 2008-2013 | 20 | 10 | A | 41 | 15 | N/A | | 13 | | Not Available | Green |
| EX3/056 | Exmouth | Marina Pens 13 & 14 | 2010-2013 | 20 | 90 | B | 374 | 46 | N/A | | 15 | | Not Available | Green |
| EX3/057 | Exmouth | Marina - Canal | 2008-2013 | 38 | 10 | A | 140 | 10 | N/A | | 14 | | Not Available | Green |
| HA3/020 | Harvey | Myalup Beach | 2009-2013 | 15 | 16 | A | 140 | 10 | Outstanding | | 13 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| HA3/021 | Harvey | Binningup Beach | 2009-2013 | 15 | | A | | 10 | Moderate | Rainfall | 13 | Collect min 5-10 rainfall (24-48hrs) samples | Good (a) | Green |
| IR3/001 | Irwin | Nunns Pool | 2009-2013 | 20 | 10 | A | 43 | 18 | Moderate | Rainfall | 15 | Collect min 5-10 rainfall (24-48hrs) samples | Good (a) | Green |
| IR3/060 | Irwin | South Beach | 2009-2013 | 20 | 85 | B | 401 | 39 | Outstanding | | 15 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| IR3/070 | Irwin | Grannie's Beach | 2009-2013 | 21 | 150 | B | 1904 | 84 | Outstanding | | 15 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| IR3/080 | Irwin | Marina (Boat Ramp) | 2009-2013 | 20 | | A | | 10 | Outstanding | | 15 | Provide DoH Sanitary Inspection Report | Not Available | Green |

Recreational Waters Bacterial Water Quality Sampling Program Site Status Report October 2013: Regional Recreational Waters

| Site Code | Managing Authority | Site Name | Result Years | No. Samples | 95th %tile | Microbial Assess Category | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assessment Category (SAC) | SAC Key Factor | Min No. LGA Samples Required 2013-2014 | SAC Status Comments | Provisional Classification | Provisional Colour |
|-----------|--------------------|--------------------------|--------------|-------------|------------|---------------------------|----------------------------------|---------------------------------------|------------------------------------|----------------|--|---|----------------------------|--------------------|
| GE3/001 | Greater Geraldton | Town Beach Jetty | 2009-2013 | 39 | 110 | B | 4310 | 43 | High - F/up | Storm water | 13 | Provide DoH stormwater drain monitoring results | Fair (a) | Amber |
| GE3/003 | Greater Geraldton | Point Moore North | 2009-2013 | 38 | 65 | B | 189 | 36 | Moderate - F/up | Rainfall | 14 | Collect 10 rainfall (24-48hrs) samples | Good | Green |
| GE3/005 | Greater Geraldton | Separation Point | 2009-2013 | 37 | 195 | B | 700 | 49 | Moderate - F/up | Rainfall | 14 | Collect min 5-10 rainfall (24-48hrs) samples | Good | Green |
| GE3/006 | Greater Geraldton | Back Beach | 2009-2013 | 37 | 40 | A | 130 | 23 | Moderate - F/up | Rainfall | 14 | Collect min 5-10 rainfall (24-48hrs) samples | Good | Green |
| GE3/008 | Greater Geraldton | Marina North | 2009-2013 | 39 | 2 | A | 140 | 10 | Moderate - F/up | Storm water | 13 | Provide DoH stormwater drain monitoring results | Good (a) | Green |
| GE3/010 | Greater Geraldton | Saint Georges Beach | 2009-2013 | 40 | 130 | B | 700 | 25 | Moderate - F/up | Rainfall | 13 | Collect 10 rainfall (24-48hrs) samples | Good | Green |
| GE3/012 | Greater Geraldton | Sunset Beach (Triton PI) | 2011-2013 | 14 | 105 | B | 1205 | 46 | Outstanding | | 13 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| GE3/020 | Greater Geraldton | Drummond Cove | 2009-2013 | 31 | 40 | A | 99 | 29 | Moderate - F/up | Rainfall | 13 | Collect min 5-10 rainfall (24-48hrs) samples | Good (a) | Green |
| GE3/021 | Greater Geraldton | Pages Beach North | 2009-2013 | 38 | 340 | C | 698 | 144 | Moderate - F/up | Storm water | 14 | Provide DoH stormwater drain monitoring results | Poor | Red |
| GE3/022 | Greater Geraldton | Tarcoola Beach | 2009-2013 | 37 | 145 | B | 1342 | 77 | Moderate - F/up | Rainfall | 14 | Collect 10 rainfall (24-48hrs) samples | Good | Green |
| GE3/023 | Greater Geraldton | Greenough Beach | 2009-2013 | 34 | 55 | B | 700 | 22 | Moderate - F/up | Rainfall | 16 | Collect 10 rainfall (24-48hrs) samples | Good | Green |
| GE3/024 | Greater Geraldton | Greenough River Mouth | 2009-2013 | 37 | 28 | A | 61 | 32 | High - F/up | Rainfall | 14 | Provide DoH Sanitary Inspection Report | Fair (a) | Red |
| GE3/025 | Greater Geraldton | Ellendale Pool | 2009-2013 | 36 | 370 | C | 517 | 136 | High - F/up | Rainfall | 15 | Collect 10 rainfall (24-48hrs) samples | Poor | Red |
| MD3/095 | Mandurah | Tim`s Thicket | 2008-2013 | 22 | 20 | A | 63 | 21 | N/A | | | | Not Available | Green |

Recreational Waters Bacterial Water Quality Sampling Program Site Status Report October 2013: Regional Recreational Waters

| Site Code | Managing Authority | Site Name | Result Years | No. Samples | 95th %tile | Microbial Assess Category | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assessment Category (SAC) | SAC Key Factor | Min No. LGA Samples Required 2013-2014 | SAC Status Comments | Provisional Classification | Provisional Colour |
|-----------|--------------------|--------------------------|--------------|-------------|------------|---------------------------|----------------------------------|---------------------------------------|------------------------------------|----------------|--|--|----------------------------|--------------------|
| MD3/100 | Mandurah | Melrose Boat Ramp | 2008-2013 | 21 | 80 | B | 381 | 36 | N/A | | | | Not Available | Green |
| MD3/105 | Mandurah | Pyramids Beach | 2008-2013 | 21 | 38 | A | 140 | 21 | N/A | | | | Not Available | Green |
| MD3/110 | Mandurah | Westview Parade (Avalon) | 2008-2013 | 21 | 45 | B | 145 | 26 | N/A | | | | Not Available | Green |
| MD3/120 | Mandurah | Falcon Beach | 2008-2013 | 88 | 8 | A | 37 | 16 | Moderate | Rainfall | 5 | Collect min 5-10 rainfall (24-48hrs) samples | Good (a) | Green |
| MD3/135 | Mandurah | Gretel Road | 2008-2013 | 22 | 40 | A | 140 | 10 | N/A | | | | Not Available | Green |
| MD3/145 | Mandurah | Janis Street | 2008-2013 | 22 | 45 | B | 221 | 16 | N/A | | | | Not Available | Green |
| MD3/150 | Mandurah | Blue Bay Leighton Road | 2008-2013 | 22 | | A | | 10 | N/A | | | | Not Available | Green |
| MD3/155 | Mandurah | Halls Head Parade | 2008-2013 | 91 | 36 | A | 115 | 22 | Moderate | Rainfall | 13 | Collect min 5-10 rainfall (24-48hrs) samples | Good (a) | Green |
| MD3/165 | Mandurah | Orion Road | 2008-2013 | 20 | 7 | A | 140 | 10 | N/A | | | | Not Available | Green |
| MD3/175 | Mandurah | Eros Place San Remo | 2008-2013 | 20 | 6 | A | 34 | 14 | N/A | | | | Not Available | Green |
| MD3/180 | Mandurah | Madora Beach | 2008-2013 | 20 | 40 | A | 228 | 10 | N/A | | | | Not Available | Green |
| MD3/200 | Mandurah | Mary Street Lagoon | 2008-2013 | 28 | 22 | A | 67 | 20 | N/A | | | | Not Available | Green |
| MD3/206 | Mandurah | Mandurah Quay Marina | 2008-2013 | 25 | 5 | A | 33 | 19 | N/A | | | | Not Available | Green |
| MD3/280A | Mandurah | East Port | 2008-2013 | 27 | 45 | B | 111 | 31 | N/A | | | | Not Available | Green |

Recreational Waters Bacterial Water Quality Sampling Program Site Status Report October 2013: Regional Recreational Waters

| Site Code | Managing Authority | Site Name | Result Years | No. Samples | 95th %tile | Microbial Assess Category | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assessment Category (SAC) | SAC Key Factor | Min No. LGA Samples Required 2013-2014 | SAC Status Comments | Provisional Classification | Provisional Colour |
|-----------|--------------------|-------------------------|--------------|-------------|------------|---------------------------|----------------------------------|---------------------------------------|------------------------------------|----------------|--|--|----------------------------|--------------------|
| MD3/280B | Mandurah | East Port | 2008-2013 | 26 | 55 | B | 135 | 35 | N/A | | | | Not Available | Green |
| MD3/287 | Mandurah | North Port | 2008-2013 | 25 | 70 | B | 303 | 34 | N/A | | | | Not Available | Green |
| MD3/310 | Mandurah | Marina Beach | 2008-2013 | 89 | 4 | A | 29 | 15 | Moderate | Rainfall | 5 | Collect 5 rainfall (within 24hrs) samples | Good (a) | Green |
| MD3/315 | Mandurah | Town Beach | 2008-2013 | 88 | 12 | A | 55 | 10 | Moderate | Rainfall | 13 | Collect min 5-10 rainfall (24-48hrs) samples | Good (a) | Green |
| MD3/330 | Mandurah | Hall Park | 2008-2013 | 88 | 18 | A | 55 | 23 | Moderate | Rainfall | 13 | Collect min 5-10 rainfall (24-48hrs) samples | Good (a) | Green |
| MD3/375A | Mandurah | Mariners Cove | 2008-2013 | 25 | 2 | A | 15 | 13 | N/A | | | | Not Available | Green |
| MD3/375B | Mandurah | Mariners Cove | 2008-2013 | 25 | 90 | B | 246 | 49 | N/A | | | | Not Available | Green |
| MD3/400 | Mandurah | Southport | 2008-2013 | 22 | 2 | A | 140 | 13 | N/A | | | | Not Available | Green |
| MD3/401 | Mandurah | Aztec Island | 2008-2013 | 27 | 3 | A | 27 | 15 | N/A | | | | Not Available | Green |
| MD3/402 | Mandurah | Henry Sutton Grove | 2008-2013 | 27 | 16 | A | 54 | 17 | N/A | | | | Not Available | Green |
| MD3/403 | Mandurah | Montreal Bay | 2008-2013 | 27 | 2 | A | 21 | 13 | N/A | | | | Not Available | Green |
| MD3/404 | Mandurah | Leslie Street Boat Ramp | 2008-2013 | 25 | 4 | A | 31 | 17 | N/A | | | | Not Available | Green |
| MD3/405 | Mandurah | Mandurah Ocean Marina | 2011-2013 | 14 | 18 | A | 140 | 10 | N/A | | | | Not Available | Green |
| MD3/410 | Mandurah | North Port | 2008-2013 | 89 | 20 | A | 58 | 24 | Moderate | Rainfall | 13 | Collect min 5-10 rainfall (24-48hrs) samples | Good (a) | Green |

Recreational Waters Bacterial Water Quality Sampling Program Site Status Report October 2013: Regional Recreational Waters

| Site Code | Managing Authority | Site Name | Result Years | No. Samples | 95th %tile | Microbial Assess Category | 1-off Trigger Level (99th %tile) | 2-in-a-row Trigger Level (90th %tile) | Sanitary Assessment Category (SAC) | SAC Key Factor | Min No. LGA Samples Required 2013-2014 | SAC Status Comments | Provisional Classification | Provisional Colour |
|-----------|--------------------|---------------------------------|--------------|-------------|------------|---------------------------|----------------------------------|---------------------------------------|------------------------------------|----------------|--|--|----------------------------|--------------------|
| MY3/002 | Murray | Ravenswood Hotel - Murray River | 2008-2013 | 63 | 380 | C | 2854 | 112 | Very High | Animals | 13 | Review Sanitary Inspection Category | Fair (a) | Amber |
| MY3/003 | Murray | Murray River Bend | 2008-2013 | 62 | 380 | C | 7624 | 133 | Very High | Animals | 13 | Collect 10 rainfall (24-48hrs) samples | Poor | Red |
| MY3/005 | Murray | Pinjarra Boat Ramp | 2008-2013 | 67 | 880 | D | 824 | 235 | Very High | Septics Tanks | 13 | Follow-up Re: Management Actions | Very Poor | Red |
| MY3/007 | Murray | Dwellingup Bridge | 2008-2013 | 66 | 220 | C | 190 | 80 | Very High | Animals | 13 | Collect 10 rainfall (24-48hrs) samples | Poor | Red |
| MY3/008 | Murray | Delta Drive | 2008-2013 | 62 | 270 | C | 18975 | 133 | Very High | Animals | 13 | Collect 10 rainfall (24-48hrs) samples | Poor | Red |
| MY3/009 | Murray | Lucie Hunter Park | 2008-2013 | 65 | 220 | C | 5462 | 167 | Very High | Animals | 13 | Collect 10 rainfall (24-48hrs) samples | Fair (a) | Red |
| MY3/014 | Murray | Baden Powell (2) Steps | 2008-2013 | 66 | 620 | D | 967 | 221 | Outstanding | | 13 | Provide DoH Sanitary Inspection Report | Not Available | Red |
| MY3/018 | Murray | Coopers Mill | 2009-2013 | 43 | 50 | B | 90 | 38 | Outstanding | | 13 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| MY3/020 | Murray | The Clansman | 2011-2013 | 24 | 190 | B | 412 | 89 | Outstanding | | 14 | Provide DoH Sanitary Inspection Report | Not Available | Amber |
| MY3/021 | Murray | Scarp Pool | 2011-2013 | 24 | 95 | B | 127 | 52 | Outstanding | | 14 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| WR3/002 | Waroona | Waroona Dam / Lake Navarino | 2008-2013 | 12 | 145 | B | 924 | 76 | Outstanding | | 13 | Provide DoH Sanitary Inspection Report | Not Available | Green |
| AW3/001 | West Arthur | Lake Towerrinning - Jetty 1 | 2010-2013 | 13 | 1700 | D | 65107 | 3256 | Outstanding | | 13 | Provide DoH Sanitary Inspection Report | Not Available | Red |