



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2016 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Type of Monitoring Site	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	No. Samples 2016-17
<b>Gascoyne Region</b>															
Shire of Carnarvon	Inlet	CN3/001	Carnarvon Town Beach	Program	2011-2015	45	90	B	334	45	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Carnarvon	Inlet	CN3/003	Facsine Beach	Program	2011-2015	48	40	A	94	33	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Carnarvon	Inlet	CN3/004	Before Yacht Club	Program	2011-2015	48	45	B	700	20	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Carnarvon	Inlet	CN3/005	Yacht Club	Program	2013-2015	33	30	A	140	12	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Carnarvon	Inlet	CN3/045	Fascine Jetty	Program	2011-2015	48	18	A	52	25	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Carnarvon	Ocean	CN3/046	Pelican Point Beach	Program	2011-2015	35	6	A	33	16	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	5
Shire of Carnarvon	Inlet	CN3/002	Carnarvon Town Beach (2)	Reference	2013-2015	34	50	B	700	11	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	5
Shire of Carnarvon	Inlet	CN3/006	Yacht Club Marina	Reference	2013-2015	33	16	A	48	25	Not Avail	Not Avail	Green		5
Shire of Carnarvon	Inlet	CN3/041	Northwater DB Drive	Reference	2011-2015	37	60	B	137	37	Not Avail	Not Avail	Green		5
Shire of Carnarvon	Inlet	CN3/042	Northwater Jaaga	Reference	2012-2015	39	80	B	370	39	Not Avail	Not Avail	Green		5
Shire of Carnarvon	Inlet	CN3/043	Boat Harbour Snapper Jetty	Reference	2011-2015	44	6	A	36	19	Not Avail	Not Avail	Green		5
Shire of Carnarvon	Inlet	CN3/044	Boat Harbour Wharf	Reference	2011-2015	44	5	A	32	19	Not Avail	Not Avail	Green		5
Shire of Carnarvon	Ocean	CN3/014	Coral Bay Foreshore - West	Reference							Not Avail	Not Avail			
Shire of Carnarvon	Ocean	CN3/015	Coral Bay Foreshore - Middle	Reference							Not Avail	Not Avail			



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2016 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Type of Monitoring Site	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	No. Samples 2016-17
<b>Gascoyne Region ...</b>															
Shire of Carnarvon	Ocean	CN3/016	Coral Bay Foreshore - East	Reference							Not Avail	Not Avail			
Shire of Carnarvon	River	CN3/020	Rocky Pool	Reference							Not Avail	Not Avail			
Shire of Carnarvon	River	CN3/034	Gascoyne River	Reference							Not Avail	Not Avail			
Shire of Carnarvon	River	CN3/047	Chinamans Pool	Reference	2011-2015	32	720	D	1329	271	Not Avail	Not Avail	Red		5
Shire of Exmouth	Canal	EX3/057	Canal Nr Bridge Horwood Side	Program	2011-2016	45	14	A	48	18	Moderate	Good (a)	Green	Collect 5-10 storm-water drain samples	13
Shire of Exmouth	Harbour	EX3/050	Small Boat Harbour - Boat Ramp	Program	2011-2016	38	14	A	48	21	Low	Very Good	Green		13
Shire of Exmouth	Ocean	EX3/051	Exmouth Town Beach	Program	2011-2016	39	90	B	206	50	Low	Good	Green		13
<b>Goldfields - Esperance Region</b>															
Shire of Esperance	Harbour	ES3/030	Bandy Creek Harbour	Program	2011-2016	53	250	C	1750	205	Moderate	Poor	Red	Collect 5-10 rainfall (24-48hrs) samples	13
Shire of Esperance	Ocean	ES3/031	James St Groyne	Program	2011-2016	52	120	B	272	62	Moderate	Good	Green	Collect 5-10 storm-water drain samples	13
Shire of Esperance	Ocean	ES3/032	Port Authority Beach	Program	2011-2016	51	100	B	201	53	Moderate	Good	Green	Collect 5-10 storm-water drain samples	13
Shire of Esperance	Bore	ES3/041	PB1	Reference							Not Avail	Not Avail			
Shire of Esperance	Bore	ES3/042	PB3	Reference							Not Avail	Not Avail			
Shire of Esperance	Bore	ES3/043	PB5	Reference							Not Avail	Not Avail			
Shire of Esperance	Bore	ES3/044	PB6	Reference							Not Avail	Not Avail			



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2016 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Type of Monitoring Site	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	No. Samples 2016-17
<b>Great Southern Region</b>															
City of Albany	Harbour	AC3/007	Emu Beach - Oyster Harbour	Proposed	2014-2015	8	2200	D		145	Not Avail	Not Avail	Red	Provide DOH Sanitary Inspection Report	13
City of Albany	Harbour	AC3/009	Boatshed Beach - Princess Royal Harbour	Proposed							Not Avail	Not Avail		Provide DOH Sanitary Inspection Report	13
City of Albany	Ocean	AC3/008	Ellen Cove (Jetty) - Middleton Beach	Proposed							Not Avail	Not Avail		Provide DOH Sanitary Inspection Report	13
City of Albany	Ocean	AC3/010	Frenchman Bay	Proposed							Not Avail	Not Avail		Provide DOH Sanitary Inspection Report	13
Shire of Denmark	Inlet	DK3/050	Wilson Inlet - Ocean Beach Caravan Park	Program	2012-2013	26	45	B	700	10	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Denmark	Inlet	DK3/051	Wilson Inlet - Yacht Club Gazebo	Program	2012-2016	43	190	B	836	100	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Denmark	Inlet	DK3/053	Wilson Inlet - Rivermouth Caravan Park	Program	2012-2016	43	760	D	2850	393	Not Avail	Not Avail	Red	Provide DOH Sanitary Inspection Report	13
Shire of Denmark	Inlet	DK3/055	Wilson Inlet - Springdale Beach 6	Program	2012-2013	25	100	B	333	52	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Denmark	River	DK3/054	Denmark River - Berridge Park	Program	2012-2016	43	1350	D	2355	466	Not Avail	Not Avail	Red	Provide DOH Sanitary Inspection Report	13
Shire of Denmark	Creek	DK3/024	Peaceful Bay - Creek/Drain	Reference	2014-2016	11	460	C	1000	194	Not Avail	Not Avail	Amber		5
Shire of Denmark	Creek	DK3/052	Creek - Inlet Drive Bridge 3	Reference	2013-2013	13	520	D	586	164	Not Avail	Not Avail	Red		0
Shire of Denmark	Drain	DK3/023	Peaceful Bay Open Drain - Foot Bridge	Reference	2014-2016	11	2800	D	2555	635	Not Avail	Not Avail	Red		5
Shire of Denmark	Drain	DK3/042	Nornalup - Drain Outlet	Reference	2014-2016	11	980	D	997	268	Not Avail	Not Avail	Red		5



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2016 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Type of Monitoring Site	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	No. Samples 2016-17
<b>Great Southern Region ...</b>															
Shire of Denmark	Ocean	DK3/025	Peaceful Bay - Ocean	Reference	2011-2016	26	55	B	177	31	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	5
Shire of Denmark	Ocean	DK3/025A	Peaceful Bay - Ocean (South)	Reference	2011-2016	26	85	B	700	19	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	5
Shire of Denmark	Ocean	DK3/025B	Peaceful Bay - Ocean (North)	Reference	2011-2016	26	38	A	140	19	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	5
Shire of Denmark	River	DK3/003	Denmark River Rivermouth	Reference							Not Avail	Not Avail			
Shire of Denmark	River	DK3/056	Hay River Bridge 7	Reference							Not Avail	Not Avail			
Shire of Denmark	River	DK3/057	Denmark River - Riverbend Lane 8	Reference							Not Avail	Not Avail			
<b>Kimberley Region</b>															
Shire of Halls Creek	Lake	HC3/002	Lake Komaterpila	Proposed							Not Avail	N/A			5
Shire of Halls Creek	Pool	HC3/001	Caroline Pool	Proposed							Not Avail	N/A			5
Shire of Halls Creek	River	HC3/003	Palm Springs	Proposed							Not Avail	N/A			5
Shire of Halls Creek	Stream	HC3/004	Sawpit Gorge	Proposed							Not Avail	N/A			5



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2016 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Type of Monitoring Site	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	No. Samples 2016-17
<b>Midwest Region</b>															
City of Greater Geraldton	Ocean	GE3/001	Town Beach Jetty	Program	2011-2016	43	2	A	12	11	High	Good (a)	Green	Collect 5-10 storm-water drain samples	5
City of Greater Geraldton	Ocean	GE3/003	Point Moore North	Program	2011-2016	41	65	B	216	33	Moderate	Good	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Greater Geraldton	Ocean	GE3/005	Separation Point	Program	2011-2014	27	70	B	126	43	Moderate	Good	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Greater Geraldton	Ocean	GE3/006	Back Beach	Program	2011-2016	40	85	B	700	22	Moderate	Good	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Greater Geraldton	Ocean	GE3/008	Marina North	Program	2011-2016	43	2	A	23	15	Moderate	Good (a)	Green	Collect 5-10 storm-water drain samples	5
City of Greater Geraldton	Ocean	GE3/010	Saint Georges	Program	2011-2016	43	9	A	140	20	Moderate	Good (a)	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Greater Geraldton	Ocean	GE3/012	Sunset Beach - Triton Pl	Program	2011-2016	38	75	B	282	36	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
City of Greater Geraldton	Ocean	GE3/021	Pages Beach North	Program	2011-2016	43	260	C	716	123	Moderate	Poor	Red	Collect 5-10 storm-water drain samples	13
City of Greater Geraldton	Ocean	GE3/022	Tarcoola Beach	Program	2011-2016	40	50	B	161	25	Very Low	Good	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Greater Geraldton	Ocean	GE3/023	Greenough Beach	Program	2011-2016	40	24	A	140	18	Moderate	Good (a)	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Greater Geraldton	Ocean	GE3/026	Drummonds Cove	Program	2011-2014	23	45	B	106	32	Moderate	Good	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Greater Geraldton	River	GE3/024	Greenough River Mouth	Program	2011-2016	43	125	B	700	47	High	Fair (a)	Amber	Collect 5-10 rainfall (24-48hrs) samples	13
City of Greater Geraldton	River	GE3/025	Ellendale Pool	Program	2011-2016	42	350	C	512	132	High	Poor	Red	Collect 5-10 rainfall (24-48hrs) samples	13
City of Greater Geraldton	River	GE3/020	Chapman River	Reference							Not Avail	N/A			

## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2016 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Type of Monitoring Site	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	No. Samples 2016-17
<b>Midwest Region ...</b>															
Shire of Irwin	Marina	IR3/080	Marina (Boat Ramp)	Program	2011-2016	26	32	A	140	10	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Irwin	Ocean	IR3/001	Nunns Pool	Program	2011-2016	26	80	B	700	10	Moderate	Good	Green	Collect 5-10 rainfall (within 24hrs) samples	13
Shire of Irwin	Ocean	IR3/060	South Beach	Program	2011-2016	26	14	A	49	19	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Irwin	Ocean	IR3/070	Grannie's Beach	Program	2011-2016	26	22	A	140	10	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
<b>Peel Region</b>															
City of Mandurah	Canal	MD3/330	Hall Park	Program	2011-2016	71	36	A	91	28	Moderate	Good (a)	Green	Collect 5-10 rainfall (24-48hrs) samples	13
City of Mandurah	Estuary	MD3/411	Eastern Foreshore	Program	2013-2016	36	32	A	83	27	Moderate	Good (a)	Green	Collect 5-10 rainfall (24-48hrs) & storm-water samples	13
City of Mandurah	Marina	MD3/310	Marina Beach	Program	2011-2016	72	2	A	17	12	Moderate	Good (a)	Green	Collect 5-10 rainfall (within 24hrs) samples	5
City of Mandurah	Ocean	MD3/120	Falcon Beach	Program	2011-2016	72	6	A	34	14	Moderate	Good (a)	Green	Collect 5-10 rainfall (within 24hrs) samples	5
City of Mandurah	Ocean	MD3/155	Halls Head Parade	Program	2011-2016	72	55	B	156	33	Moderate	Good	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Mandurah	Ocean	MD3/315	Town Beach	Program	2011-2016	72	24	A	215	20	Low	Very Good	Green*		5
City of Mandurah	Ocean	MD3/410	North Port	Program	2011-2016	72	10	A	43	19	Moderate	Good (a)	Green	Collect 5-10 rainfall (24-48hrs) samples	13
City of Mandurah	Canal	MD3/287	North Port	Reference	2011-2016	22	6	A	31	12	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	5
City of Mandurah	Canal	MD3/280A	East Port	Reference	2011-2016	27	38	A	140	20	Not Avail	Not Avail	Green		5



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2016 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Type of Monitoring Site	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	No. Samples 2016-17
<b>Peel Region ...</b>															
City of Mandurah	Canal	MD3/280B	East Port	Reference	2011-2016	26	115	B	223	58	Not Avail	Not Avail	Green		5
City of Mandurah	Canal	MD3/375A	Mariners Cove	Reference	2011-2016	27	2	A	21	15	Not Avail	Not Avail	Green		5
City of Mandurah	Canal	MD3/375B	Mariners Cove	Reference	2011-2016	22	115	B	430	59	Not Avail	Not Avail	Green		5
City of Mandurah	Canal	MD3/401	Aztec Island	Reference	2011-2016	27	4	A	30	15	Not Avail	Not Avail	Green		5
City of Mandurah	Canal	MD3/403	Monterey Bay	Reference	2011-2016	27	16	A	53	17	Not Avail	Not Avail	Green		5
City of Mandurah	Canal	MD3/404	Leslie Street Boat Ramp	Reference	2011-2016	27	5	A	31	15	Not Avail	Not Avail	Green		5
City of Mandurah	Estuary	MD3/200	Mary Street Lagoon	Reference	2011-2016	27	26	A	140	10	Not Avail	Not Avail	Green		5
City of Mandurah	Estuary	MD3/400	Southport	Reference	2011-2016	23	2	A	20	12	Not Avail	Not Avail	Green		5
City of Mandurah	Estuary	MD3/402	Henry Sutton Grove	Reference	2011-2016	27	5	A	31	12	Not Avail	Not Avail	Green		5
City of Mandurah	Marina	MD3/206	Mandurah Quay Marina	Reference	2010-2015	33	2	A	21	15	Not Avail	Not Avail	Green		5
City of Mandurah	Marina	MD3/405	Mandurah Ocean Marina	Reference	2011-2016	27	3	A	24	12	Not Avail	Not Avail	Green		5
City of Mandurah	Ocean	MD3/095	Tim`s Thicket	Reference	2011-2013	8	50	B	117	32	Not Avail	Not Avail	Green		5
City of Mandurah	Ocean	MD3/100	Melrose Boat Ramp	Reference	2011-2013	8	8	A	38	19	Not Avail	Not Avail	Green		5
City of Mandurah	Ocean	MD3/105	Pyramids Beach	Reference	2011-2016	24	22	A	67	18	Not Avail	Not Avail	Green		5

## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2016 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Type of Monitoring Site	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	No. Samples 2016-17
<b>Peel Region ...</b>															
City of Mandurah	Ocean	MD3/110	Westview Parade (Avalon)	Reference	2011-2016	24	2	A	140	21	Not Avail	Not Avail	Green		5
City of Mandurah	Ocean	MD3/135	Gretel Road	Reference	2011-2013	8	16	A	140	10	Not Avail	Not Avail	Green		5
City of Mandurah	Ocean	MD3/145	Janis Street	Reference	2011-2013	8	30	A	140	10	Not Avail	Not Avail	Green		5
City of Mandurah	Ocean	MD3/150	Blue Bay Leighton Road	Reference	2011-2016	19		A		10	Not Avail	Not Avail	Green		5
City of Mandurah	Ocean	MD3/165	Orion Road	Reference	2011-2016	24	2	A	21	12	Not Avail	Not Avail	Green		5
City of Mandurah	Ocean	MD3/175	Eros Place San Remo	Reference	2011-2016	24	24	A	140	21	Not Avail	Not Avail	Green		5
City of Mandurah	Ocean	MD3/180	Madora Beach	Reference	2011-2016	24	34	A	140	10	Not Avail	Not Avail	Green		5
Shire of Murray	Inlet	MY3/018	Coopers Mill	Program	2011-2016	59	90	B	862	41	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Murray	River	MY3/002	Ravenswood Hotel - Murray River	Program	2011-2016	59	195	B	229	80	Very High	Fair (a)	Amber	Review Sanitary Inspection Category	13
Shire of Murray	River	MY3/003	Murray River Bend	Program	2011-2016	59	200	B	406	92	Very High	Fair (a)	Amber	Collect 5-10 rainfall (24-48hrs) samples	13
Shire of Murray	River	MY3/005	Pinjarra Boat Ramp	Program	2011-2016	64	540	D	527	160	Very High	Very Poor	Red	Follow-up Re: Management Actions	5
Shire of Murray	River	MY3/007	Dwellingup Bridge	Program	2011-2016	63	55	B	82	42	Very High	Fair (a)	Amber	Collect 5-10 rainfall (24-48hrs) samples	13
Shire of Murray	River	MY3/008	Delta Drive	Program	2011-2016	59	105	B	21393	52	Very High	Fair (a)	Amber	Collect 5-10 rainfall (24-48hrs) samples	13
Shire of Murray	River	MY3/009	Lucie Hunter Park	Program	2011-2016	64	85	B	131	50	Very High	Fair (a)	Amber	Collect 5-10 rainfall (24-48hrs) samples	13
Shire of Murray	River	MY3/014	Baden Powell (2) Steps	Program	2011-2016	63	430	C	604	155	Not Avail	Not Avail	Amber	Provide DOH Sanitary Inspection Report	13





## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2016 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Type of Monitoring Site	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	No. Samples 2016-17
<b>Peel Region ...</b>															
Shire of Murray	River	MY3/020	The Clansman	Program	2011-2016	64	50	B	93	38	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Murray	River	MY3/021	Scarp Pool	Program	2011-2016	63	65	B	108	43	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Waroona	Lake	WR3/001	Drakesbrook Dam / Lake Moyanup	Proposed	2012-2016	12	300	C	430	116	Not Avail	Not Avail	Amber	Provide DOH Sanitary Inspection Report	13
Shire of Waroona	Lake	WR3/002	Waroona Dam / Lake Navarino	Proposed	2011-2016	12	65	B	236	32	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
<b>Pilbara Region</b>															
Shire of Ashburton	Lake	AN3/001	Kings Lake Recreation Area	Reference							Not Avail	Not Avail			
<b>South West Region</b>															
Shire of Augusta-Margaret River	Inlet	AM3/023	Hardy Inlet - Turner Caravan Park	Program	2011-2016	66	450	C	792	175	Not Avail	Not Avail	Amber	Provide DOH Sanitary Inspection Report	13
Shire of Augusta-Margaret River	Ocean	AM3/012	Gnarabup Beach (Jetty)	Program	2011-2016	65	95	B	427	47	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Augusta-Margaret River	Ocean	AM3/014	Gracetown Beach	Program	2011-2016	66	34	A	103	23	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Augusta-Margaret River	Ocean	AM3/016	Flinders Bay - Redman Brook	Program	2011-2016	66	45	B	480	10	Moderate	Good (a)	Green	Collect 5-10 rainfall (within 24hrs) & riverine samples	13
Shire of Augusta-Margaret River	River	AM3/001	Margaret River - Canoe Landing	Program	2011-2016	63	240	C	539	108	Not Avail	Not Avail	Amber	Provide DOH Sanitary Inspection Report	13



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2016 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Type of Monitoring Site	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	No. Samples 2016-17
<b>South West Region ...</b>															
Shire of Augusta-Margaret River	River	AM3/006	Margaret River - Barrett St Weir	Program	2011-2016	65	105	<b>B</b>	142	55	Not Avail	Not Avail	<b>Amber</b>	Provide DOH Sanitary Inspection Report	13
Shire of Augusta-Margaret River	River	AM3/044	Margaret River - Rendall CI Weir	Program	2014-2016	<b>25</b>	30	<b>A</b>	78	26	Not Avail	Not Avail	<b>Green</b>	Provide DOH Sanitary Inspection Report	13
Shire of Augusta-Margaret River	Drain	AM3/024	Hardy St Drain	Reference							Not Avail	Not Avail			
Shire of Augusta-Margaret River	Inlet	AM3/022	Colour Patch Drain Foreshore	Reference							Not Avail	Not Avail			
Shire of Augusta-Margaret River	Inlet	AM3/060	Molloy Island - Sandy beach	Reference							Not Avail	Not Avail			
Shire of Augusta-Margaret River	Inlet	AM3/061	Molloy Island - Canal	Reference							Not Avail	Not Avail			
Shire of Augusta-Margaret River	River	AM3/009	Margaret River - Town Bridge	Reference							Not Avail	Not Avail			
Shire of Augusta-Margaret River	River	AM3/021	Molloy Island - Caravan Park	Reference							Not Avail	Not Avail			
Shire of Augusta-Margaret River	River	AM3/048	Molloy Island - The Basin	Reference							Not Avail	Not Avail			
Shire of Augusta-Margaret River	River	AM3/049	Molloy Island - Sandy Beach	Reference							Not Avail	Not Avail			



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2016 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Type of Monitoring Site	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	No. Samples 2016-17
<b>South West Region ...</b>															
City of Bunbury	Harbour	BC3/001	Jetty Bath West	Program	2011-2016	60	60	B	5196	30	Moderate	Good	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Bunbury	Ocean	BC3/012	Koombana Beach	Program	2011-2016	59	20	A	60	23	Moderate	Good	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Bunbury	Ocean	BC3/017	Surf Club Beach	Program	2011-2016	60	2	A	30	10	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	5
City of Bunbury	Ocean	BC3/018	Hungry Hollow	Program	2011-2016	61	34	A	249	10	Moderate	Good (a)	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Bunbury	Ocean	BC3/025	Ski Beach	Program	2011-2016	59	2	A	31	10	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	5
City of Bunbury	Drain	BC3/023	Meredith Creek Compensation Basin	Reference							Not Avail	Not Avail			
City of Bunbury	Drain	BC3/028	Queens Gardens	Reference							Not Avail	Not Avail			
City of Bunbury	Drain	BC3/029	Queens Pump	Reference							Not Avail	Not Avail			
City of Bunbury	Drain	BC3/030	Blair St Canal	Reference							Not Avail	Not Avail			
City of Bunbury	Estuary	BC3/002	Estuary Plug	Reference							Not Avail	Not Avail			
City of Bunbury	Estuary	BC3/003	Rowing Club	Reference							Not Avail	Not Avail			
City of Bunbury	Estuary	BC3/004	Bunbury Yacht Club	Reference							Not Avail	Not Avail			
City of Bunbury	Estuary	BC3/005	Meredith Creek	Reference							Not Avail	Not Avail			
City of Bunbury	Estuary	BC3/006	Parade Hotel	Reference							Not Avail	Not Avail			
City of Bunbury	Estuary	BC3/007	Sofilas	Reference							Not Avail	Not Avail			



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2016 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Type of Monitoring Site	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	No. Samples 2016-17
<b>South West Region ...</b>															
City of Bunbury	Estuary	BC3/010	Turkey Point	Reference							Not Avail	Not Avail			
City of Bunbury	Estuary	BC3/026	Sykes Foreshore	Reference							Not Avail	Not Avail			
City of Bunbury	Estuary	BC3/027	Canoe Launch	Reference							Not Avail	Not Avail			
City of Bunbury	Harbour	BC3/021	Harbour East	Reference							Not Avail	Not Avail			
City of Bunbury	Harbour	BC3/022	Harbour West	Reference							Not Avail	Not Avail			
City of Bunbury	Ocean	BC3/024	Maidens Park	Reference							Not Avail	Not Avail			
City of Bunbury	River	BC3/008	Preston River	Reference							Not Avail	Not Avail			
City of Bunbury	River	BC3/009	Collie River	Reference							Not Avail	Not Avail			
City of Busselton	Ocean	BN3/023	Margaret Street Beach (Site 8)	Program	2011-2016	57	165	B	316	78	Moderate	Good	Green	Collect 5-10 rainfall (24-48hrs) & riverine samples	13
City of Busselton	Ocean	BN3/024	Scout Beach (Site 6)	Program	2011-2016	58	135	B	14055	70	Moderate	Good	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Busselton	Ocean	BN3/025	Forth Street Beach (Site 7)	Program	2011-2016	58	175	B	1078	96	Moderate	Good	Green	Collect 5-10 rainfall (within 24hrs) samples	13
City of Busselton	Ocean	BN3/028	Busselton Jetty Ocean 9	Program	2011-2016	56	520	D	68377	1139	Not Avail	Not Avail	Red	Provide DOH Sanitary Inspection Report	13
City of Busselton	Creek	BN3/022	Margaret St - Creek	Reference	2011-2016	32	820	D	419	165	Not Avail	Not Avail	Red		5
City of Busselton	Creek	BN3/027	Forth St - Creek	Reference	2011-2016	32	200	B	377	90	Not Avail	Not Avail	Green		5



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2016 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Type of Monitoring Site	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	No. Samples 2016-17
<b>South West Region ...</b>															
City of Busselton	Creek	BN3/043	Wonnerup Floodgate	Reference	2015-2016	13	70	B	222	38	Not Avail	Not Avail	Green		5
City of Busselton	Creek	BN3/044	Wonnerup Inlet Road Bridge	Reference	2015-2016	13	1050	D	2150	402	Not Avail	Not Avail	Red		5
City of Busselton	Drain	BN3/021	Margaret St - Drain	Reference	2011-2016	32	980	D	79816	2328	Not Avail	Not Avail	Red		5
City of Busselton	Ocean	BN3/045	Wonnerup Inlet Ocean Mouth	Reference	2015-2016	13	50	B	98	37	Not Avail	Not Avail	Green		5
City of Busselton	Ocean	BN3/351	Port Geographe - Inlet Pool North	Reference							Not Avail	Not Avail			5
City of Busselton	Ocean	BN3/355	Port Geographe - Swimming Lagoon	Reference							Not Avail	Not Avail			5
Shire of Capel	Ocean	CP3/001	Forrest Beach	Program	2011-2016	43	860	D	3185	444	Moderate	Poor	Red	Collect 5-10 rainfall (within 24-hrs) samples	13
Shire of Capel	Ocean	CP3/002	Peppermint Grove Beach	Program	2011-2016	43	50	B	700	12	Moderate	Good	Green	Collect 5-10 rainfall (within 24-hrs) samples	13
Shire of Capel	Ocean	CP3/003	Minninup Beach	Program	2011-2016	43	240	C	696	116	Moderate	Good	Green	Collect 5-10 rainfall (within 24-hrs) samples	13
Shire of Capel	Ocean	CP3/004	Dalyellup Beach	Program	2011-2016	43	75	B	431	32	Moderate	Good (a)	Green	Collect 5-10 rainfall (within 24-hrs) samples	13
Shire of Capel	Ocean	CP3/007	Water Corp Dalyellup Beach	Program							Not Avail	Not Avail		Provide DOH Sanitary Inspection Report	13
Shire of Capel	Ocean	CP3/008	North Dalyellup Beach	Program							Not Avail	Not Avail		Provide DOH Sanitary Inspection Report	13



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2016 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Type of Monitoring Site	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	No. Samples 2016-17
<b>South West Region ...</b>															
Shire of Capel	River	CP3/005	Preston River - Boyanup	Program	2011-2016	42	2400	D	1443	432	Not Avail	Not Avail	Red	Provide DOH Sanitary Inspection Report	5
Shire of Capel	River	CP3/006	Capel River - Mallokup Bridge	Program	2011-2016	42	155	B	210	70	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Collie/ Department of Lands	Lake	CI3/003	Black Diamond Recreational Water Area	Program	2015-2016	11	2	A	140	14	Not Avail	Not Avail	Green		13
Shire of Collie/ DPaW	Reservoir	CI3/001	Potters Gorge - Wellington Dam	Program							Low	Not Avail	Green	Collect 5-10 rainfall (24-48hrs) samples	13
Shire of Collie/ DPaW	River	CI3/002	Honeymoon Pool - Preston River	Program							Moderate	Not Avail	Amber	Collect 5-10 rainfall (24-48hrs) samples	13
Shire of Donnybrook-Balingup	River	DB3/013	Preston River - Donnybrook Amphitheatre	Reference							Not Avail	Not Avail			
Shire of Donnybrook-Balingup	River	DB3/014	Preston River - Footbridge	Reference							Not Avail	Not Avail			
Shire of Harvey	Lake	HA3/027	Lake Brockman Boat Ramp	Program	2014-2016	17	2	A	16	12	Moderate	Good (a)	Green	Collect 5-10 rainfall (24-48hrs) & riverine samples	13
Shire of Harvey	Ocean	HA3/020	Myalup Beach	Program	2011-2016	33	2	A	16	10	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	5
Shire of Harvey	Ocean	HA3/021	Binningup Beach	Program	2011-2016	33	45	B	700	10	Moderate	Good	Green	Collect 5-10 rainfall (within 24hrs) samples	13
Shire of Harvey	Reservoir	HA3/026	Harvey Dam Boat Ramp	Program	2015-2016	14	50	B	183	25	Moderate	Good	Green	Collect 5-10 rainfall (24-48hrs) samples	13
Shire of Manjimup	Reservoir	MJ3/1811	Fonty's Pool - SE Cnr Pool (near outlet)	Proposed							Not Avail	Not Avail			13



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview November 2016 - Regional Local Government Authorities

LGA/ Managing Authority	Water Body	Site Code	Site Name	Type of Monitoring Site	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category (SAC)	Provisional Class	Provisional Colour	SAC Status Actions	No. Samples 2016-17
<b>Wheatbelt Region ...</b>															
Shire of Dandaragan	Harbour	DA3/006	Jurien Boat Harbour Beach (West)	Program	2011-2016	31	55	B	122	37	Moderate	Good	Green	Collect 5-10 rainfall (within 24hrs) samples	13
Shire of Dandaragan	Harbour	DA3/007	Jurien Boat Harbour Beach (East)	Program	2011-2016	30	30	A	81	26	Moderate	Good (a)	Green	Collect 5-10 rainfall (within 24hrs) samples	13
Shire of Dandaragan	Ocean	DA3/013	Dobbyn Park Beach	Program	2011-2016	31	8	A	37	18	Moderate	Good (a)	Green	Collect 5-10 rainfall (within 24hrs) samples	5
Shire of Dandaragan	Ocean	DA3/015	Cervantes - Swimming Beach	Program	2012-2016	24	55	B	151	34	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	13
Shire of Dandaragan	Ocean	DA3/016	Cervantes - Jetty/Boat Ramp	Program	2012-2016	24	2	A	21	14	Not Avail	Not Avail	Green	Provide DOH Sanitary Inspection Report	5
Shire of Dandaragan	Lake	DA3/012	Namming Lake	Reference							Not Avail	Not Avail			
Shire of Gingin	River	GG3/001	Moore River - Mouth Beach	New							Not Avail	Not Avail		Provide DOH Sanitary Inspection Report	13
Shire of Gingin	River	GG3/002	Moore River - Caravan Park	New							Not Avail	Not Avail		Provide DOH Sanitary Inspection Report	13
Shire of Gingin	River	GG3/003	Moore River - Boat Ramp	New							Not Avail	Not Avail		Provide DOH Sanitary Inspection Report	13
Shire of Gingin	River	GG3/010	Moore River Desert Boardwalk	New							Not Avail	Not Avail		Provide DOH Sanitary Inspection Report	13
Shire of Gingin	Ocean	GG3/011	Lancelin Grace Darling Park Beach	Proposed							Not Avail	N/A			
Shire of Gingin	Ocean	GG3/012	Lancelin Harold Park Beach	Proposed							Not Avail	N/A			
Shire of West Arthur/ DPaW	Lake	AW3/001	Lake Towerrinning - Jetty 1	Program	2011-2016	28	1550	D	21044	1620	Moderate	Poor	Red	Collect 5-10 rainfall (24-48hrs) samples	13
Shire of West Arthur/ DPaW	Lake	AW3/002	Lake Towerrinning - Caravan Park	Program	2013-2016	21	1350	D	1837	411	Not Avail	Not Avail	Red	Provide DOH Sanitary Inspection Report	13